

## Wyr-Grid<sup>®</sup> Tools and Hardware

**HNLW12****FR716DR****WGCT-A****WGCT-M**

Part Number	Part Description	Std. Pkg. Qty.	Std. Ctn. Qty.
<b>Hardware</b>			
<b>HNLW12</b>	1/2-13 hex nut and 1/2 lock washer for use in attaching trapeze brackets to threaded rod.	100	—
<b>HNLW12M</b>	12mm hex nut and 12mm lock washer for use in attaching trapeze brackets to threaded rod.	100	—
<b>Tools</b>			
<b>FR716DR</b>	7/16" nut driver for use with the FiberRunner <sup>®</sup> , GridRunner <sup>™</sup> , and Wyr-Grid <sup>®</sup> Systems.	1	10
<b>WGCT-A</b>	Battery powered cutting tool for cutting Wyr-Grid <sup>®</sup> Cable Trays, 2 – 18 volt lithium-ion batteries, and 115 volt, 60 Hz charger included.	1	—
<b>CD-WGCD-1</b>	Wyr-Grid <sup>®</sup> Replacement Cutting Die for the automatic cutting tool.	1	—
<b>WGCT-HEAD</b>	Wyr-Grid <sup>®</sup> Replacement Cutting Head for the automatic cutting tool.	1	—
<b>WGCT-M</b>	Manual cutting tool for cutting Wyr-Grid <sup>®</sup> Cable Trays. Weight: 5.4 lbs. (2.45 kg)	1	—